



A Sonova brand








Day 1 after removal






Day 3 after removal






Day 6 with oil






Day 6 after cleaning






Day 1 after removal






Day 4 after removal






Day 60 after removal




Case #2

Day 60 after cleaning






Day 61 with oil




Case #2

Day 61 after cleaning






Day 1 after sizing




Case #3

Day 12 after placement






Day 55 after removal






Day 63 after replacement and forceful removal






Day 4 after removal




Case #3

Day 6 after removal




Case #3

Day 58 after replacement and removal




Case #3

Day 61 after replacement and removal






Day 6 after removal






Day 45 after replacement and removal






Day 1 after placement






Day 3 after removal






Day 4 after removal




Case #4

Day 14 after removal




Case #4

Day 26 after replacement and removal






Day 1 after removal




Case #5

Day 4 after removal




Case #5

Day 61 after replacement and removal




Case #5

Day 94 after replacement and removal




Case #5

Day 96 after removal with oil




Case #5

Day 157 after replacement and removal




Case #5

Day 203 after replacement and removal






Day 1 before placement






Day 74 after removal





Day 10 after removal





Day 10 after cleaning

Together, we change lives